

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives	Present	Durina	the I	nspection:

OGM Karl Houskeeper Environmental Scientist III

# **Inspection Report**

Permit Number:	C0150015
Inspection Type:	COMPLETE
Inspection Date:	Thursday, May 06, 2010
Start Date/Time:	5/6/2010 8:00:00 AM
End Date/Time:	5/6/2010 2:20:00 PM
Last Inspection:	Thursday, April 01, 2010

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: <u>Clear, Temp. 50 Deg. F.</u> InspectionID Report Number: <u>2348</u>

**Types of Operations** 

Reprocessing

Accepted by: jhelfric

5/17/2010

Permitee: CONSOLIDATION COAL CO

Operator: CONSOLIDATION COAL CO SESSER OPERATIONS

Site: EMERY DEEP MINE

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

#### **Current Acreages**

442.50	<b>Total Permitted</b>
248.50	<b>Total Disturbed</b>
	Phase I
	Phase II
	Phase III

#### Mineral Ownership

☐ Other

✓ Federal
✓ Underground

□ State
□ Surface

□ County
□ Loadout

✓ Fee
□ Processing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Jaren Jorgensen, Conso, I was present during the inspection.

Inspector's Signature:

Harl R. Musbayse er, Environmental Scientist III

Date

Thursday, May 06, 2010

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0150015 Inspection Type: COMPLETE

Inspection Date: Thursday, May 06, 2010

Page 2 of 4

### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
   For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Entorcement
1.	Permits, Change, Transfer, Renewal, Sale	<b>✓</b>		$\checkmark$	
2.	Signs and Markers	<u> </u>			
3.	Topsoil	<b>V</b>		<b>✓</b>	
4.a	Hydrologic Balance: Diversions	<b>✓</b>		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	<b>✓</b>		<b>✓</b>	
4.c	Hydrologic Balance: Other Sediment Control Measures	<b>✓</b>			
4.d	Hydrologic Balance: Water Monitoring	<b>✓</b>			
4.e	Hydrologic Balance: Effluent Limitations	<b>✓</b>		<b>V</b>	
5.	Explosives	<b>✓</b>			
6.	Disposal of Excess Spoil, Fills, Benches	<b>✓</b>			
7.	Coal Mine Waste, Refuse Piles, Impoundments	<b>✓</b>		<b>V</b>	
8.	Noncoal Waste	<b>V</b>		<b>✓</b>	
9.	Protection of Fish, Wildlife and Related Environmental Issues	<b>V</b>			
10.	Slides and Other Damage	<b>✓</b>			
11.	Contemporaneous Reclamation	<b>V</b>			
12.	Backfilling And Grading	<b>V</b>			
13.	Revegetation	✓			
14.	Subsidence Control	<b>V</b>			
15.	Cessation of Operations	<b>~</b>			
16.8	a Roads: Construction, Maintenance, Surfacing	<u> </u>			
16.Ł	Roads: Drainage Controls	<b>✓</b>			
17.	Other Transportation Facilities	~			
18.	Support Facilities, Utility Installations	~			
19.	AVS Check	<b>✓</b>			
20.	Air Quality Permit	<b>✓</b>		<b>✓</b>	
21.	Bonding and Insurance	<b>✓</b>		<b>✓</b>	
22.	Other	<b>V</b>			

Permit Number: C0150015
Inspection Type: COMPLETE

Inspection Date: Thursday, May 06, 2010

Page 3 of 4

### 1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit C/015/015 was issued effective 01/06/2006 and expires 01/08/2011.

- -Certificate of Insurance policy number BOG 9377 215-06, issued 11/05/2009 and terminates 11/05/2010.
- -UPDES permit UT-0022616 effective 12/01/2006 and expires @ midnight 11/30/2011.
- -Air Quality permit DAQE-AN0229006-05, issued July 20, 2005.
- -SPCC Plan dated 10/24/06. The Plan is P.E. certified, stamped, signed and dated by a Utah P.E.

### 3. Topsoil

The topsoil sign located by the portal access road that is to be placed on top of the berm is down. The sign needs to be put back into place so that mine personnel are aware that this a topsoil stoage area and is not to be disturbed.

Mine beltin is laid against the berm that is alos a topsoil pile. The belting needs to be removed from off the topsoil storage.

### 4.a Hydrologic Balance: Diversions

The belting has been removed from the diversion that was identified on the previous inspection.

### 4.b Hydrologic Balance: Sediment Ponds and Impoundments

First quarter 2010 pond inspections were done on 03/29/2010.

# 4.e Hydrologic Balance: Effluent Limitations

The March 2010 discharge monitoring reports were reviewed as part of the complete inspection. The TDS loading parameter was exceeded. The company notified DEQ of the exceedance by letter dated April 28, 2010.

### 7. Coal Mine Waste, Refuse Piles, Impoundments

The first quarter 2010 refuse pile inspection was done on 02/14/2010 and P.E. certified.

#### 8. Noncoal Waste

High winds were present during the inspection. Portions of the main facility and 4th East Portal area had scattered trash. These areas were identified and the operator committed to remove the trash immediately.

### 20. Air Quality Permit

The Air Quality Permit Approval Order DAQE-AN0229006-05 was issued on July 20, 2005. The permit remains effective.

**Inspection Continuation Sheet** 

Permit Number: C0150015
Inspection Type: COMPLETE

Inspection Date: Thursday, May 06, 2010

Page 4 of 4

## 21. Bonding and Insurance

Bond #188617 December 3, 2008 is \$3,510,000.